

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 30-31

CORNER MONUMENT 1" Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED May 10, 1962 with E. Eckart, A.D.F.

WITNESSES TO CORNER..... 8" Cedar (1/4S NBT) S 69° W 30 Links



6" Cedar (1/4S NBT) S 2° E 22 Links

Squared and scribed 5" Black Spruce at Corner.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one W.Pine B.T. bearing S 15° W 18 links. B.T. is a rotted stub 3' high with lower half of upper face and bottom notch.

Stub in poor condition.

Corner found by Ed. Eckart, A.D.F.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE March 16, 1964
REGISTERED LAND SURVEYOR
Billy D. Buckler