Coss. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W

			Mackinac Mackinac	COUNTY
DESCRIPTION OF CORNER	East 1/16 Cor	ner of Section	n 33	
CORNER MONUMENT	Pipe with 4" Alu	minum Cap		
DATE MONUMENT PLACED A	MD WITHESSED10/	24/63 with Ed	Eckart, Assistant Foreste	er
WITHESSES TO CORNER	6 W. Pine	(E1/16BT) N2	3°W 44½ Lks.	-
N 930	Corner lies 1	.90 chains No	rth of Road	
CINCLE CONNER RESISTER	AND			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway between 1/4 Corner to East and Center of Section to West.

SURVEYOR'S SEAL

Silly E. Suchler
SIENED BILLY D. BUCKLER

DATE 7/30/1964