

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 & 8 W


Mackinac COUNTY

DESCRIPTION OF CORNER S 1/16 corner T43N R8W 12/7 T43N R7W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/20/66, Frank J. Bray

WITNESSES TO CORNER..... 5" Balsam (S1/16)(BT) S 75° W, 04 Links



CIRCLE CORNER REGISTERED

7" Cedar (S1/16)(BT) N 49° E, 32 Links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner to south and 1/4 corner to north.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/28/67
REGISTERED LAND SURVEYOR