LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T N. R E. W.		
2. PROPERTY CONTROLL- CING IN SECTION—	, T. 43 N., R. 7 W.	F3-2, F3-5	
3. MISCELLANEOUS PROPERTY IN SECTION —	, T N., R E.		
6. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAN

- A. Description of original monument and accessories and/or subsequent restoration:
- F3-2 Witness corner 870.65! East of North 1/4 Section 9. Not prev. set.
- P3-5 Witness corner 460.48' South of North 1/4 Section 9. Not prev. set.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- F3-2 Corner set on east side Strouble Lake on north side of section 9.
- F3-5 Corner set on south side of Strouble Lake on N-S 1/4 line.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR monument set at both corners. Bearings:

SIGNED BY and B. Balfett

David B. Babbitt

DATE 8-18-83

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)