LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

2 Corners

· ·	Killac Co.	L 00		
FOR CORNERS OF -:	LOCATED IN-:	CORNER	CODE NUMBER	
1. PUBLIC LAND SURVEY_	T. 43 N., R. 7	t. F-2	···	
2. PROPERTY CONTROLL- ING IN SECTION-	4 ,T. 43 N. R. 7	: 12-3F	 .	
	, T	L.	·	
4. LOT NO,	RECORDED PLAT	· · · · · · · · · · · · · · · · · · ·		
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned re-established, monumented and rules therefore as requi	in lines 1 and 2 above were, in, re-monumented, recovered or red in the current manual of sur	a field survey restored as exp rvey instruction	on 1-4 & 1- pressed below and s of the United S	f P.A. 74, Michigan P.A. of 1970, 5, 1984, established, in conformance with regulations tates Department of the Interior,
and 5 above were, in a field	survey on	_, 19, fou	nd, recovered, rest	points mentioned in lines 3, 4 ored, established or re-established ation for Land Surveyors or, by a
	nonument and accessories and/o		storation:	
12-3F Witness Corner	- 1264.34' North of Sou	ith 1/4 Cor	ner of Sectio	n 4. Not prev. set.
F-2 Corner set at	idence found and/or method ap intersection of N-S ar North side Strouble La	nd E-W 1/4	lines by clos	ed traverse.
C. Description of monumer D.N.R. Monument set a F-2 6" Tamarack, N24 3" Tamarack, N63 3" Tamarack, "514	10W, 16.2' 30E, 3.5'	ings: 12-3F	30" W. Pine, 12" Hemlock, 10" W. Birch,	S47 ⁰ E, 23.4' S79 ⁰ E, 26.2' N16 ⁰ E, 28.3'
4" Tamarack, S30 SIGNED BY David B.			8" R. Maple, 	N62 ⁰ W, 20.5'

FOR STATE AND UNITED STATES ACENCIES:

SURVEYOR'S MICHIGAN REGISTRATION NO.