

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner Common to Secs. 3-4-9-10

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5-29-68

WITNESSES TO CORNER..... 5" B.Spruce (S3 NBT) N56°E 26.4'



13" W.Birch (S10 NBT) S12°E 18.9'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established between corners to north and south. Distance to corner 1 mile east checks also ties to west are good. No evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
Billy D. Buckler R.L.S. DATE 10-8-68  
REGISTERED LAND SURVEYOR