

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER ½ Corner between Sections 9 & 10

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5-29-68

WITNESSES TO CORNER..... 8" Cedar (½S NBT) N10°W 17.2'



CIRCLE CORNER REGISTERED

8" Cedar (½S NBT) S72°W 6.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Sec. Corners

Found no evidence of original corner though numerous cedar and tamarack in vicinity.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler, R.L.S. DATE 10-8-68  
REGISTERED LAND SURVEYOR