

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 3-4

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-20-68

WITNESSES TO CORNER..... 9" Cedar (1/2 S NBT) N14°W 22.7'



8" Cedar (1/2 S NBT) S20°W 18.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on line between; 1/16 corner of record to north and Sec. corners to south.  
Found no evidence of the original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10-8-68  
REGISTERED LAND SURVEYOR