

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43N R. 8-9W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 13-18.

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-9-62

WITNESSES TO CORNER..... 10" Aspen (1/4S NBT) N84°W, 19 links



CIRCLE CORNER REGISTERED

Corner lies in swamp.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners.

No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 23, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler