

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43N N.R. 8-9W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 19-24

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-26-62

WITNESSES TO CORNER..... 10" Soft Maple (1/2 S NBT) S11°W, 40 links



CIRCLE CORNER REGISTERED

8" Y. Birch (1/2 S NBT) N40°W, 83 1/2 links

Corner lies 35 links SW of top of escarpment

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at wood post set by Marcus Schaaf, Registered Land Surveyor; found remains of large W. Pine stump at proper bearing and distance.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 24, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler