

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Secs. 27-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-22-68

WITNESSES TO CORNER..... 10" Cedar (1/2 S NBT) N22°E 3.2'



11" Cedar (1/2 S NBT) N76°E 28.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at 22" tamarack stump, a probable corner tree. Corner lies 45 links east of stream as record notes indicate. This is the only tamarack in the immediate vicinity. Found some old blazes to east and west.

Corner lies 10' south of an old E-W logging trail.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler, R.L.S. DATE 10-8-68
REGISTERED LAND SURVEYOR