

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between sections 2-34

CORNER MONUMENT 5/8" Iron bar, buried in road intersection.

DATE MONUMENT PLACED AND WITNESSED 5/14/68

WITNESSES TO CORNER..... 10" Red Pine ($\frac{1}{2}$ S NBT) N20°W 112.5'



11" Red Pine " N45°E 118.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed in center of E-W road and in line with road to south, according to road survey map by D. A. Brotherton, Land Surveyor, in 1916.

Found road traverse to south, to agree with this location.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR