

17
MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER ½ Corner between secs. 11-14

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-8-68

WITNESSES TO CORNER..... 8" Cedar (½S NBT) N47°W 4.7'



9" Cedar (½S NBT) S49°W 15.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two sec. corners. Found no evidence of 10" Spruce corner tree as recorded. Corner lies in east margin of thick cedar swamp and 30' east of an old swamp road.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler, R. L. S. DATE 10-8-68
REGISTERED LAND SURVEYOR