

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Macackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between Sections 2-21

CORNER MONUMENT 1 $\frac{1}{4}$ " x 30" pipe, buried in center of road.

DATE MONUMENT PLACED AND WITNESSED 5/22/68

WITNESSES TO CORNER..... 10" W. Pine ($\frac{1}{4}$ S NBT) N87°E 34.9'



CIRCLE CORNER REGISTERED

9" B. Spruce " S48°E 38.1'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by single proportionate measure to north and south,
and on the alignment of a North and South road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR