

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 16-17-20-21

CORNER MONUMENT 1 $\frac{1}{4}$ " x 30" pipe, buried in center of road.

DATE MONUMENT PLACED AND WITNESSED 5/22/68

WITNESSES TO CORNER..... 7" Cedar (S21 NBT) S79°E 51.0'



8" Cedar (S17 NBT) N63°W 75.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner re-established by single proportionate measure to North and South,
and on the alignment of a North and South road.**

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR