

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 8W


MacKinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 8-9-16-17

CORNER MONUMENT 1 1/4" x 30" pipe, buried in center of road.

DATE MONUMENT PLACED AND WITNESSED 5/22/68

WITNESSES TO CORNER..... 6" Cedar (S16 NBT) S42°E 69.2'



28" W. Pine Stump (S8 NBT) N60°W 81.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by single proportionate measure to North and South,
and on the alignment of a North and South Road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR