

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between Sections 8-9

CORNER MONUMENT $1\frac{1}{4}$ " x 30" Iron pipe driven in center of road.

DATE MONUMENT PLACED AND WITNESSED 5/22/68

WITNESSES TO CORNER..... 10" Soft Maple ($\frac{1}{4}$ S NBT) S78°W 102.1'



6" Cedar " N49°E 46.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner re-established by single proportionate measure to North and South,
and on the alignment of a North and South Road.**

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR