

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between sections 28-29

CORNER MONUMENT 1 $\frac{1}{2}$ " x 30" Iron pipe, buried in ~~it~~ of the Borgstrom Road.

DATE MONUMENT PLACED AND WITNESSED 5/8/68

WITNESSES TO CORNER..... 11" Cedar ($\frac{1}{4}$ S NBT) N70°E 44.0'



12" Spruce ($\frac{1}{4}$ S NBT) S62°W 64.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in center of road on an old line to West. Distance North checks to stream and section corner.

Placed location post 17.0' West of corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR