Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T. 43 N. R. 8W	^r ackinac	COUNTY
DESCRIPTION OF CORNER _	1/4 Corner between Sections 23-24		
CORNER MONUMENT	1" pipe with 4" aluminum cap.		
DATE MONUMENT PLACED AND	WITHESSED		
WITHESSES TO CORNER	30" W. Pine (\frac{1}{4}S NBT) N33 W 51.2"		
23	15" W. Pine " S2°E 32.71	 	. <u>.</u>
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Squared and scribed 7" Spruce at corner. This corner re-established midway and on line between two section corners.

No evidence of original corner. Found some very old blazes on large W. Pine which I marked as a new witness to N.W.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler, R.L.S. DATE 9/25/68

REGISTERED LAND SURVEYOR