

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 8W


MacKinnac COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  Corner between Sections 22-23

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5/14/68

WITNESSES TO CORNER..... 5" Cedar ( $\frac{1}{4}$ S NBT) N46°E 22.1'



6" Soft Maple ( $\frac{1}{4}$ S NBT) S42°E 27.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners.

Found no evidence of original corner or witnesses.

Corner lies 1 chain south of the old Stage Road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler, R.L.S. DATE 9/25/68  
REGISTERED LAND SURVEYOR