

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner common to sections 1-2-35-36

CORNER MONUMENT 5/8" Iron bar, buried in road intersection.

DATE MONUMENT PLACED AND WITNESSED 5/14/68

WITNESSES TO CORNER..... 16" W. Spruce (S35 NBT) 37°W 62.0'



U. S. Geological Survey Monument T82S bearing

N25°E 70.6'.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in road intersection and 50.8' south of a culvert.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler, R.L.S. DATE 9/25/68  
REGISTERED LAND SURVEYOR