

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Macackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between sections 4-5

CORNER MONUMENT 1" Pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5/8/68

WITNESSES TO CORNER..... 10" Red Pine ($\frac{1}{4}$ S NBT) N58°E 38.4'



10" Hard Maple " S70°E 41.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced 33.0' East of a fence corner.
Location checks with corners North and South for
distance and alignment.

Corner lies on East edge of road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR