

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 43N R 8W

DESCRIPTION OF CORNER North 1/16 corner between 3-4

CORNER MONUMENT 1 1/4" x 30" iron pipe, buried in E-W road.

DATE MONUMENT PLACED AND WITNESSED 4-30-68

WITNESSES TO CORNER..... _____



AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed in line with old fence line north and midway between fences along E-W road. Fences are 33' apart. Location as indicated by Road Survey, D. A. Brotherton 1916.

this is a corrected copy.
12/11/69 B.D.B.

SURVEYOR'S SEAL

Billy D. Buckler
Billy D. Buckler

SIGNED

REGISTERED LAND SURVEYOR

DATE

9-25-68

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
✓ Forestry Div., Lansing

R 4047
Rev. 10/68