

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 43-44N R 8W

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 36-1

CORNER MONUMENT 5/8" iron pin, driven in centerline of E-W road

DATE MONUMENT PLACED AND WITNESSED 4-10-69

WITNESSES TO CORNER..... 15" H. Maple N19°W 39.1'



8" H. Maple N34°E 54.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in intersection of E-W road and road to north.
Found interior corners to north (Sec. 36, T44N R8W) to agree with this
location.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-24-69
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing