

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 8-9W


Mackinac COUNTY

DESCRIPTION OF CORNER ½ Corner between Secs. 1-6

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-20-68

WITNESSES TO CORNER..... 7" Cedar (½S NBT) N7°W 28.7'



8" Cedar (½S NBT) N33°E 40.0'

AND

CIRCLE CORNER REGISTERED

### DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on north bank of stream in accord with record notes, which indicate three stream crossings in 4.50 chains to south.  
Found stream in a well-defined gully with limestone ledge rock.  
Definitely in the same location as in 1840.  
Found no evidence of the original corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 10-8-68  
Billy D. Buckler, R.L.S.  
REGISTERED LAND SURVEYOR