

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Secs. 1-2

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/68

WITNESSES TO CORNER..... 9" Cedar (1/2 S NBT) S36°W 17.2'



8" Cedar (1/2 S NBT) N48°W 3.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established between two sec. corners.
Found no evidence of original corner or witnesses.
Distance north to Swamp edge checks well.
Corner lies in a thick cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 10-8-68
REGISTERED LAND SURVEYOR