

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{2}$ Corner between secs. 8-17

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-2868

WITNESSES TO CORNER..... 7" Balsam ($\frac{1}{2}$ S NBT) S50°E 34.1'



6" B.Spruce ($\frac{1}{2}$ S NBT) S82°E 56.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between two sec. corners.
Distance west to stream checks well.
Found no evidence of corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 10-8-68
REGISTERED LAND SURVEYOR