

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Corner common to Secs. 17-18-19-20

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-28-68

WITNESSES TO CORNER..... 10" Soft Maple (S18 NBT) N62°W 11.0'



10" Soft Maple (S19 NBT) S14°W 26.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by double proportionate measure, using corners in all four directions. Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 10-8-68
REGISTERED LAND SURVEYOR