

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner common to Secs. 10-11-14-15

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-22-68

WITNESSES TO CORNER..... 7" cedar (S14 NBT) S40°E 5.8'



8" cedar (S11 NBT) N33°E 12.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one original witness; a cedar stub, bearing N62°W 13 lks.

Found part of upper blaze with several scribe marks and lower blaze intact.

Found no evidence of use at this corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9-20-68
REGISTERED LAND SURVEYOR