

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 84


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between Secs. 6-7.

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-3-68

WITNESSES TO CORNER..... 11" Y. Birch (NBT) S24°W 29.6°



CIRCLE CORNER REGISTERED

7" Y. Birch (NBT) S31°E 46.8°

Concrete project marker S87°W 36.1°

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as set by D.A. Brotherton, Land Surveyor in 1916.

Found Hemlock stump with witness marks, bearing S25°W 39.5°; a blaze, notch with a nail and metal disc. Found remains of Hemlock S12°E 68.2°

Corner lies in line with road to north and northeast.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9-20-68
REGISTERED LAND SURVEYOR