

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 23-24-25-26

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-29-68

WITNESSES TO CORNER..... 12" B. Spruce (NBT) N9°E 37.4'



10" W. Pine (S26 NBT) S85°W 42.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in old road bed and 25' north of present road bed.

This corner re-established according to notes by Marcus Schaaf, R.L.S. Schaaf found this corner about 1937. Road construction apparently obliterated the monument.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9-20-68
REGISTERED LAND SURVEYOR