

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 22-23-26-27

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 4-26-68

WITNESSES TO CORNER..... 10" tamarack (S 26 NBT) S 32°E 23.8°



10" spruce (S 27 NBT) S 27°W 27.5°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one original witness; a 14" cedar, bearing N 29° E, 12 links.
Tree is down, both faces evident and in fair condition.

Found wood post set by Marcus Schaaf, R.L.W.

Corner lies on a small island in wet cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9-23-68
REGISTERED LAND SURVEYOR