

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 20-21-28-29

CORNER MONUMENT 1" Pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 4/30/68

WITNESSES TO CORNER..... 9" Twin W. Pine (S21 NBT) N1°E 15.0'



12" W. Birch (NBT) S72°E 51.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 30' East of LC Worth Road and 25' South of gasline clearing.

This corner replaced as found by Marcus Schaaf, R.L.S. about 1937.

Found old wood post in place.
Location agrees with notes by Schaaf.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler R.L.S. DATE 9/25/68
REGISTERED LAND SURVEYOR