

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER ¼ Corner between Secs. 2-11

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-4-68

WITNESSES TO CORNER..... 9" Hard Maple (½S NBT) S75°W 13.2'



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Sec. Corners.

No evidence of original corner.

Corner lies 120' north of truck trail.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R. L. S. DATE 10-8-68
REGISTERED LAND SURVEYOR