

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Secs. 24-25

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-4-68

WITNESSES TO CORNER.....12" W. Pine (1/2 S NBT) S41°W 41.0'



5" Soft Maple (1/2 S NBT) N42°W 18.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners.

No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R. L. S. DATE 10-8-68
REGISTERED LAND SURVEYOR