

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Secs. 16-21

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-13-68

WITNESSES TO CORNER..... 6" Cedar (1/2 S NBT) S25°W 37.3'



16" W.Pine stump (1/2 S NBT) N16°W 19.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies on south slope of a steep ridge, 1/2 chain north of swamp edge.
Corner placed at record distance to west of section corner.
No evidence of original corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler, R.L.S. DATE 10-8-68
REGISTERED LAND SURVEYOR