LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co. 1 Corner

FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 43 N. X, R. 8 E. W.	F-3
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-27-, 19 74, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Quarter Corner bet. Sec's. 4-9, set by H. Brevoort Jr., D.S. in 1845. Bearings were: Beech 10", N6°E, 57 lks. and Hemlock 10", S56°W, 38 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner re-established midway and on line between two Section Corners. No evidence of original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at corner. New Bearings: 8" W. Birch, S30°E, 18.6' and 6" Twin B. Spruce, N24°E, 13.9'.

SIGNED BY Billy D. Buckler DATE 7-15-81

STATE OF MICHIGAN BILLY D. BUCKLER LAND SURVEYOR NO. 8887 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887