

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 9 W


Mackinac COUNTY

DESCRIPTION OF CORNER S 1/16 corner for Sections 25-26

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/30/64 with Forestry Aide Burnis

WITNESSES TO CORNER..... 5" Cedar (S 1/16 BT), N 18° E, 08 lks.



6" Cedar (S 1/16 BT), S 41° W, 45½ lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was placed midway and on line between 1/4 Corner to North and Section Corner to South.

**SURVEYOR'S SEAL**

SIGNED Frank J. Bray DATE 12/8/1964  
REGISTERED LAND SURVEYOR