

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 9W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 22-23

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 2/13/64

WITNESSES TO CORNER..... 8" Cedar (1/8 S NBT) S20°E 42 1/2 Lrs.



22" W. Pine (1/8 S NBT) N55°W 21 1/2 Lrs.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from Wood Post and buried 1 1/2" iron pipe in a 6" cube of concrete, placed by Marcus Schaaf, Registered Land Surveyor. Both B.M.'s found but in poor condition.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/11/1964
REGISTERED LAND SURVEYOR