

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 43N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs' 8-9-16-17

CORNER MONUMENT Iron, buried in center of road

DATE MONUMENT PLACED AND WITNESSED 5/20/71

WITNESSES TO CORNER..... 10" W. Spruce (S8 NBT) N72°W 40.0'



14" W. Spruce (S17 NBT) S68°W 40.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner witnessed as placed by unknow surveyor.
Found iron in center of road with a wood post on east side of road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 2/17/72
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓