## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 43 N. R. 11 %.	E-5, B-7	•
2. PROPERTY CONTROLL- ING IN SECTION	N. E. V. S., R. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. E. V.		
4. LOT NO, RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
the corner points mentioned in li- re-established, monumented, re-rand rules therefore as required in Bureau of Land Management or and 5 above were, in a field surve	nes 1 and 2 above were, in a finonumented, recovered or result the current manual of survey by a decree of a court of law.	tored as expressed below and reinstructions of the United St. Furthermore, that the corner [9, found, recovered, restored.	F.A. 74, Michigan P.A. of 1970,  ———————————————————————————————————
A. Description of original monu-	ment and accessories and/or su	bsequent restoration:	
North 1/4 cor. of sec	. 18. Wood Post, Spr	uce 6", N58 <sup>0</sup> W, 11 lks	. & Tam6", S55°E, 23 1ks.
South 1/4 cor. of sec	. 18. Wood Post, Fir	4", N50°E, 16 lks. &	Fir 6", South, 32 lks.
B. Description of corner evidence			
Set by single proport	ion to G.L.O. record	between the N.W. and 1	N.E. sec. cors. of sec. 18.
Sat M.P.O.L. between mile as 80.00 chs.)		. cors. of sec. 18. (	G.L.O. record shows this
C. Description of monument for	corner and accessories establis	shed to perpetuate locating the	position of the corner:
D.N.R. Monument. New	Learings: B	-7 D.N.R. Monument.	New Bearings:
10" W. Fine, N64°E, 8" W. Fine, N80°E, 10" W. Fine, N28°W,	159.21 194.91 67.71	4" Cedar, SO9 <sup>°</sup> W 6" Cedar, S20° <b>E</b> 8" Cedar, S77°E	34.5 <sup>1</sup> 23.3 <sup>1</sup> 55.1 <sup>1</sup>
Carner lies in open m	arch.		
SIGNED BY David E. Rab	B. Ballit	DATE 4-21-8	2

FOR STATE AND UNITED STATES AGENCIES:

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

-5

-7

-5

-7

-5