

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 12 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Cor. bet. Sess. 27-28.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 9-29-69

WITNESSES TO CORNER..... 14" Soft Maple (1/8 NBT) Due East 34.0'



13" Soft Maple (1/8 NBT) N25°E 23.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old Axle Shaft placed by unknown Surveyor. Found this shaft on an old brushed line, direction North & South.

Corner lies 97.0' North of Stack Grade.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1-12-70
REGISTERED LAND SURVEYOR