

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

3 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>43</u> N. S. R. <u>12</u> E. W.	<u>L-10, L-9</u>
2. PROPERTY CONTROLLING IN SECTION <u>25</u>	T. <u>43</u> N. S. R. <u>12</u> E. W.	<u>5</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6-9-, 19 87, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- L-10 Center of Section 25. Not previously set.
- L-9 North 1/4 Corner of Section 25. OBT'S: Cedar 6, S73°E, 35 lks. & Cedar 10, S35°W, 13 lks.
- 5 North 1/16 Corner of Section 25. Not previously set.


B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- L-10 Corner set at intersection of North - South and East - West 1/4 Line of Section 25 by closed traverse.
- L-9 Corner set M.P.O.L. between N.W. Corner and S.E. corner of Section 25.
- 5 Corner set M.P.O.L. between Center Corner and North 1/4 corner of Section 25.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L-10 & 5 DNR Monument, L-9 1" pipe w/plastic cap.
- | | | |
|--------------------------------|----------------------------|------------------------------|
| L-10 12" W. Birch, S21°E, 7.1' | L-9 5" Cedar, S35°E, 9.65' | 5 14" W. Birch, S67°W, 15.7' |
| 8" Cedar, S18°E, 22.6' | 5" Cedar, S12°W, 21.95' | 6" Maple, S48°W, 29.2' |
| 10" Cedar, S51°W, 29.2' | 6" Cedar, S26°W, 11.8' | 8" Maple, N28°W, 11.1' |
| 12" Cedar, N33°W, 25.7' | 6" Cedar, S74°W, 16.1' | 6" W. Birch, S65°E, 10.9' |

SIGNED BY Gerald L. Wiggins DATE 9-8-87
 Gerald L. Wiggins
 SURVEYOR'S MICHIGAN REGISTRATION NO. 23521



FOR STATE AND UNITED STATES AGENCIES: