

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Mackinac
County

Located In: _____ Corner Code 77

1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S <u>34</u> T <u>43N</u> R <u>12W</u>	M.C. <u>4-5</u>
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	1	2	3	4	5	6	7	8	9	10	11	12	13
3	14	15	16	17	18	19	20	21	22	23	24	25	26
4	27	28	29	30	31	32	33	34	35	36	37	38	39
5	40	41	42	43	44	45	46	47	48	49	50	51	52
6	53	54	55	56	57	58	59	60	61	62	63	64	65
7	66	67	68	69	70	71	72	73	74	75	76	77	78
8	79	80	81	82	83	84	85	86	87	88	89	90	91
9	92	93	94	95	96	97	98	99	100	101	102	103	104
10	105	106	107	108	109	110	111	112	113	114	115	116	117
11	118	119	120	121	122	123	124	125	126	127	128	129	130
12	131	132	133	134	135	136	137	138	139	140	141	142	143
13	144	145	146	147	148	149	150	151	152	153	154	155	156

I, Gerald L. Wiggins in a field survey on 5-3, 19 90, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Meander Corner on the North 1/16 line of Section 34 on East side of lake. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner set on East edge of Milakokia Lake on North 1/16 line of Section 34 2980.50' from North 1/16 Corner on East side of Section 34.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR Monument with Tags in bottom of witness trees.


8" W. Pine, N37°W, 27.0' & 8" Cedar, N28°E, 42.9' & 12" Maple, N84°E, 72.35' & 10" W. Pine, S70°E, 15.85'

Signed by

Gerald L. Wiggins

Date 9-13-90

Surveyor's Michigan License No. 23521



FORM APPROVED BY MICHIGAN BOARD OF LAND SURVEYORS, JAN. 20, 1971
 REVISED MAY 14, 1979
 REVISED JAN., 1983