COMMISSION

1993 Mackinac County Remonumentation Corner

Surveyor's Michigan License No. \_\_\_\_22435

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in	Filing Requirem	ent of Act 74, Mich. P.A. 19	70
Mackinac	Located In:	Corner Code ##	
(County)	<del></del>		DYANG CRAFTERSON
1. Public Land Survey	T 43N_R2W_	G-3	WYCHOLA C COLLEGE LARGERILL COS DEEDS
	T R T R		OCT 2 8 1993
•	Ť R		AM 7[8[9]10[15]12[1]4[8[4]5]6
Property Controlling     in Section	S T R S T R		Vidiatre sair attaining
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No, I	Recorded Plat		— ABCDEFGHIJKLM
5. Private Claims	:		2 6 5 4 3 2
	ı		3
		02	4 7 1 8 9 10 10 11 12 12
Javid B. Guthrie	., in a field survey on <u>June 8</u> equirements of P.A. 74, Michigan P.A. of 1	, 19 <u>93</u> , 1970, the corner points mentioned	5
in lines 1 and 2 above were	in conformance with regulations and re	ules therefore as required in the	7
Management or by a decree of	ructions of the United States Departme f a Court of Law and/or that the corner po	oints mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
above were in conformance w	ith the rules of the Michigan Board of Lare-established, monumented, re-mor	and Surveyors or by a Decree of a numented, recovered, found as	9
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town and	range, may be recorded	12 31 32 33 34 35 36
•	1		13
A. Description of original	monument and accessories and/o	or subsequent restoration:	at wood post and referenced
1845: Establish	r Maple - N37°W - 35	Links/18" Sugar Ma	et wood post and referenced aple - S43°W - 8 Links.
1971: Survey by	Mary C. Feindt.		
1972: Survey by	C. Eugene Ostling.	Iondlund & Aggos f	For II S. Forest Service
1987: Survey by	Kichard L. Hays of F	Widiana & Assoc. 1	For U.S. Forest Service.
* . * * * * * * * * * * * * * * * * * *	I i		
	· ·		
B. Description of corner	evidence found and/or method app	plied in restoring or reestablish	ning corner:
1993: Found 2½"	x 3' aluminum monume the corner. This corr	ent with a 3" alumi her was set in 1989	inum cap stamped to 9 by Richard L. Hays
P.S. No.	25847, to replace an	8" spike which was	s compatible with pre-
vious refe	erences by C. Eugene	Ostling (Book A, I	page 38- 1972) and corner was recorded on
January 3	, 1989. (Book D, page	e 39)	
Plat of S	urvey Recorded as U.	S. Gov't. Plat of	Survey No. 14.
	· ·		
	1		
	1		
C. Description of monum	nent for corner and accessories est	tablished to perpetuate locatin	g the position of the corner:
1993: N15°W -	22.15 feet - (R=22.48	') - 7" Maple	
N71°E -	24.47 feet - (R=24.58 19.99 feet (R=19.73'	') - 8" Maple	SE OF MICH
S50°E -	48.35 feet - (R=48.0'	) - 24" Cedar	Est. Garage
s58°W -	25.25 feet - (R=25.21	') - 7" Maple	A DAVID B.
	5.20 feet - Steel Po		LAND SURVEYOR
The monu	ment is a 2½"x3' alu	minum monument wit	n a 3" 22435 129
aruminum (Tree re	cap stamped to iden eferences are blazed	and tagged.)	William SURVE
	· ·		THAT Y
Signed by $\mathcal{N}$	3. tile		t. 27 ,1993
Signed by	<del></del>		<i>'</i>

D-0198