

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 7 W.


Chippewa-Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 25-30

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/25/63

WITNESSES TO CORNER..... 8" Cedar (1/4 S. N.B.T.) N. 10° W. 12 Lks.



7" Cedar (1/4 S. N.B.T.) S. 86° W. 25 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established by single proportionate measure along township line. Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 1/27/64
REGISTERED LAND SURVEYOR