

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 6 - 7 West

-----Mackinac----- COUNTY

DESCRIPTION OF CORNER section corner for sections 7 - 12 - 13 - 13 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 2-4-58 -----

6" cedar S 81°, E 30½ links. Marked "1313P" -----

4" cedar N 27°, W 39 links. Marked "1312 PT" -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced as set by Marcus Schaaf, Regional Surveyor. Found two tamarack bearing trees, bearing S 59°, W 13 links and N 27°, E 12 links. Both bearing trees are stumps; have been chopped out. Corner shown to us by J. Halbach, District Forester.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler ----- DATE 6-18-59 -----
REGISTERED LAND SURVEYOR