

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 7 - 8 West

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 25 and 30

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 2-4-58

7" cedar (dead) S 33° E 64 links. Marked "S33BT"

5" cedar S 75° W 101 links. Marked "S75BT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced as set by Marcus Schaaf, Regional Surveyor. Found 1 1/2" iron pipe in concrete with wood post in place. Corner lies in swamp. Corner shown to us by J. Halbach, District Forester.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-18-59
REGISTERED LAND SURVEYOR