Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 7W

			COUNTY
DESCRIPTION OF CORNER	Section corner for sections	s 28-29-32-33	
CORNER MONUMENT	l" pipe with 4" brass cap		
DATE MONUMENT PLACED AND	WI THESSED		
WITHESSES TO CORNER	No witnesses available	e . Corner lies in open bog.	
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old tamarack post which agrees with good corners 1 mile north and 1 mile south.

No evidence of original corner but did find old squared tamarack stub at corner.

SHRYEYOR'S SEAL

SIGNED Silly S. Suckles DATE March 13, 1962

REGISTERED LAND SURVEYOR

Billy D. Buckler