LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R E		
2. PROPERTY CONTROLL- ING IN SECTION—	23., T. 44. N. R. 7. W	1	
3. MISCELLANEOUS PROPERTY IN SECTION —	,T		• •
4. LOT NO, R	ECORDED PLAT	·	
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Gerald L. Wiggi	ns do hereby	certify that under requirements a field survey on	of P.A. 74, Michigan P.A. of 1970

- A. Description of original monument and accessories and/or subsequent restoration:
- 1 North 1/16 Corner on West side of Section 23. Not previously set.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1 Corner set M.P.O.L. between N.W. Corner and West 1/4 Corner of Section 23.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 DNR Monument placed at corner.

12" Cedar, N83°W. 20.2' 5" Cedar, N42°E, 16.1'

5" Cedar, N82°E, 6.95'

4" Cedar, S13°E, 10.95'

SIGNED BY Level & Wiggins

DATE 9-21-87

GERALD L.
WIGGINS
LAND
SURVEYOR
No.
23521

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521

FOR STATE AND UNITED STATES AGENCIES: